

# RELEASE NOTES

---



## COMPASS 4.2.3 UPDATES FOR GALAXY

Compass 4.2.3 software requires the following firmware versions:

- GALAXY Firmware v1.2.4 (All models)
- Bluehorn 816 v1.2.4
- RMServer v2.2.3
- CAL v1.3.3

## FIRMWARE UPDATE - FLASH MEMORY HARDWARE

GALAXY units running firmware version 1.2.3 should be upgraded to version 1.2.4, which adds protection from downgrading the firmware to a version that is incompatible with the new hardware. The functionality of 1.2.4 is otherwise identical to version 1.2.3.

## CONTROLLER MODES

GALAXY Internal controller mode will only work when making connections to other GALAXY devices. If you wish to connect to a third-party device, you will need to use the external controller mode to make AVB connections.

## KNOWN ISSUES

Using an Apple computer with AVB capabilities to make AVB connections to GALAXY will produce unexpected and undesirable results. It is strongly recommended to avoid AVB connections to or from an Apple computer.



Meyer Sound Laboratories Inc.  
2832 San Pablo Avenue  
Berkeley, CA 94702  
[www.meyersound.com](http://www.meyersound.com)  
+1 510 486.1166

*Compass 4.2.3 Release Notes*  
©2017 Meyer Sound. All rights reserved.

*The contents of this document are furnished for informational purposes only, are subject to change without notice, and should not be construed as a commitment by Meyer Sound Laboratories Inc. Meyer Sound assumes no responsibility or liability for any errors or inaccuracies that may appear in this document. Except as permitted by applicable copyright law, no part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, recording or otherwise, without prior written permission from Meyer Sound.*