

RELEASE NOTES



COMPASS 4.3.2 UPDATES FOR GALAXY, CAL, AND RMSERVER

Compass 4.3.2 software requires the following firmware versions:

- GALAXY Firmware v1.3.2 (All models)
- Bluehorn 816 v1.3.2
- RMServer v2.3.1
- CAL v1.4.0

COMPASS FEATURES & ENHANCEMENTS

Firmware Hotfix (Addresses Real Time Clock Hardware Field Kit: MSPN 40.230.029.01):

- This version of Compass allows the installation of updated embedded firmware to support the RTC hardware field replacement kit. This update is only required if your GALAXY or Bluehorn Processor serial number is less than:
 - 18138357 - (GALAXY 816)
 - 18138483 - (GALAXY 816 AES)
 - 18138395 - (GALAXY 408)
 - 18139315 - (Bluehorn 816)
- Please contact Meyer Sound Service for more information: service@meyersound.com.

BUG FIXES

- Fixed a bug that occurred when upgrading a GALAXY from any previous version to 1.3.0. Migration of the project file when opened would corrupt the matrix inserts AVB configuration. This corruption will prevent the user from saving the AVB configuration for any of the matrix inserts or input "A." Affected users can recover their project by installing the this update and reloading the project that was saved under version 1.2.4 or older.



Meyer Sound Laboratories Inc.
2832 San Pablo Avenue
Berkeley, CA 94702
www.meyersound.com
+1 510 486.1166

Compass 4.3.2 Release Notes
©2018 Meyer Sound. All rights reserved.

The contents of this document are furnished for informational purposes only, are subject to change without notice, and should not be construed as a commitment by Meyer Sound Laboratories Inc. Meyer Sound assumes no responsibility or liability for any errors or inaccuracies that may appear in this document. Except as permitted by applicable copyright law, no part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, recording or otherwise, without prior written permission from Meyer Sound.