RELEASE NOTES

Compass 4.8.3 Updates for GALAXY and RMServer



Compass 4.8.3 software requires the following firmware versions:

- GALAXY Firmware v2.3.3 (All models)
- RMServer v2.8.0
- CAL v2.2.0

GALAXY SPACEMAP MODE

Improvements:

Crossfade from trajectory to static position now respects Spacemap boundary.

Labels are now stored in Channel Snapshots for linked channels.

User is now prevented from inadvertently stacking nodes in Create View.

Mono linked channels playback improved in Overview during a trajectory.

Smoother trajectory playback improvements when using the app in sub-optimal network conditions.

RMSERVER

Added support for IntelligentDC (MPS-488HP with RMS option) Products: ULTRA-X20XP, X22XP, X23XP, USW-112XP

COMPASS

Added support for IntelligentDC (MPS-488HP with RMS option) Products: ULTRA-X20XP, X22XP, X23XP, USW-112XP

The contents of this document are furnished for informational purposes only, are subject to change without notice, and should not be construed as a commitment by Meyer Sound Laboratories Inc. Meyer Sound assumes no responsibility or liability for any errors or inaccuracies that may appear in this document. Except as permitted by applicable copyright law, no part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, recording or otherwise, without prior written permission from Meyer Sound. Compass 4.8.3 Release Notes Meyer Sound Laboratories, Inc. +1 510 486.1166 2832 San Pablo Avenue 05.230.121.23 A www.meyersound.com/contact

