

RELEASE NOTES

Compass 4.9.0 Updates for Loudspeakers, GALAXY and RMServer



Compass 4.9.0 software requires the following firmware versions:

- GALAXY Firmware v2.4.0 (All models)
- RMServer v2.9.0
- CAL v2.2.0

GALAXY FIRMWARE

Improvements to Spacemap Mode to support clocking from an AES input

Users are now able to enter the IPv4 address of a Spacemap Go system, which is useful in the event that an IPv6 network is not available.

Spacemap Mode will not allow entity and group names to be changed by Compass or third-party controllers to avoid any chance of interruptions during a performance or trajectory playback.

RMSERVER

Added product support for Ultra Reflex LF-18

Added product support for X-1100C

COMPASS

Added RMS support for Ultra Reflex LF-18

Added RMS support for X-1100C

The contents of this document are furnished for informational purposes only, are subject to change without notice, and should not be construed as a commitment by Meyer Sound Laboratories Inc. Meyer Sound assumes no responsibility or liability for any errors or inaccuracies that may appear in this document. Except as permitted by applicable copyright law, no part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, recording or otherwise, without prior written permission from Meyer Sound.
