

### UPDATES / FIXES

---

- Updated the Entity-Model ID to avoid controller enumeration issues
- Fixed a problem with the Galileo GALAXY control plane text interface related to a fix in the previous firmware version (2.8.0) where the cluster names were fixed
- Fixed issues related to adding PANTHER to Low-Mid Beam Control (LMBC) configuration
- Disabled Multiple MAC Registration Protocol (MMRP) function as it was not used and can cause issues in certain networks

*The contents of this document are furnished for informational purposes only, are subject to change without notice, and should not be construed as a commitment by Meyer Sound Laboratories Inc. Meyer Sound assumes no responsibility or liability for any errors or inaccuracies that may appear in this document. Except as permitted by applicable copyright law, no part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, recording or otherwise, without prior written permission from Meyer Sound.*

---