RELEASE NOTES

Compass 4.8.1 Updates for GALAXY, CAL, and RMServer

Compass 4.8.1 software requires the following firmware versions:

- GALAXY Firmware v2.3.1 (All models)
- RMServer v2.7.0
- CAL v2.2.0

GALAXY (SPACEMAP MODE)

Performance improvements made to the core engine for Spacemap Mode which allow smoother fades and faster response time throughout the Matrix when working with Trajectories and Matrix Channel Mutes and Solos.

The contents of this document are furnished for informational purposes only, are subject to change without notice, and should not be construed as a commitment by Meyer Sound Laboratories Inc. Meyer Sound assumes no responsibility or liability for any errors or inaccuracies that may appear in this document. Except as permitted by applicable copyright law, no part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, recording or otherwise, without prior written permission from Meyer Sound.

Meyer Sound Laboratories, Inc.
2832 San Pablo Avenue
Berkeley, CA 94702

+1 510 486.1166
www.meyersound.com/contact
www.meyersound.com

Compass 4.8.1 Release Notes
05.230.121.21 A
Copyright © 2020. All Rights Reserved.