RELEASE NOTES

COMPASS 4.6.1 UPDATES FOR GALAXY, CAL, AND RMSERVER

Compass 4.6.1 software requires the following firmware versions:

- GALAXY Firmware v2.1.0 (All models)

- Bluehorn 816 v2.1.0

- CAL v2.1.1

- RMServer v2.6.1

Firmware NOT Supported in Compass 4.6.1:

- GALAXY v1.3.4 or earlier

- Galileo and Callisto v3.12.0 or earlier

- CAL Firmware v2.1.0 or earlier

- RMServer v2.6.0 or earlier

COMPASS FEATURES & ENHANCEMENTS

Compass now supports exclusive Milan connections to the secondary network port without requiring a physical connection to the primary network port.

Meyer Sound Laboratories Inc.
2832 San Pablo Avenue
Berkeley, CA 94702

www.meyersound.com
+1 510 486.1166