RELEASE NOTES

Compass 4.9.1 Updates for Loudspeakers, GALAXY and RMServer

Compass 4.9.1 software requires the following firmware versions:

- GALAXY Firmware v2.4.1 (All models)
- RMServer v2.9.1
- CAL v2.2.0
- ULTRA-X20/22/23 Milan v1.0.0
- USW-112P Milan v1.0.0

COMPASS

Added support for Milan Endpoint option available for Loudspeaker Products: ULTRA-X20, X22, X23, and USW-112P

Renamed the “RMServer” Tab to “Monitoring”; it provides the control interface for remote monitoring of loudspeaker products that use twisted pair RMS with RMServer, as well as Milan digital loudspeaker products that have integrated status reporting capability.

Added support for Milan AVB connection manager app which can be launched from the Compass application.

The contents of this document are furnished for informational purposes only, are subject to change without notice, and should not be construed as a commitment by Meyer Sound Laboratories Inc. Meyer Sound assumes no responsibility or liability for any errors or inaccuracies that may appear in this document. Except as permitted by applicable copyright law, no part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, recording or otherwise, without prior written permission from Meyer Sound.

Meyer Sound
2832 San Pablo Avenue
Berkeley, CA 94702

+1 510 486.1166
www.meyersound.com/contact
www.meyersound.com

Compass 4.9.1 Release Notes
05.230.121.25 A
Copyright © 2021. All Rights Reserved.