

RELEASE NOTES

Compass 4.11.0



Compass 4.11.0 software requires the following firmware versions:

- GALAXY (all models) Firmware v2.6.0 — updated for this release
- RMServer Firmware v2.9.1
- CAL Firmware v2.2.0
- Milan Endpoint Firmware v1.3.2
- Bluehorn 816 v2.6.0 — updated for this release

NOTE: If upgrading CAL from firmware version 1.5.0 or earlier, please contact Technical Support for specific instructions.

COMPASS

This version is compatible with MacOS 12 (Monterey) and Windows 11 Professional 64-bit.

Fixes:

- When using 12 ch AVB streams, noise issue resolved.
- Galileo GALAXY 408, AES clock source selection error resolved.
- Ethernet reliability improved.
- Other bug fixes.

The contents of this document are furnished for informational purposes only, are subject to change without notice, and should not be construed as a commitment by Meyer Sound Laboratories, Incorporated. Meyer Sound assumes no responsibility or liability for any errors or inaccuracies that may appear in this document. Except as permitted by applicable copyright law, no part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, recording or otherwise, without prior written permission from Meyer Sound.

