

RELEASE NOTES



COMPASS 4.2.2 UPDATES FOR CAL

Compass 4.2.2 software enhances functionality.

Compass 4.2.2 software requires the following firmware versions:

- GALAXY Firmware v1.2.2 (All models)
- Bluehorn 816 v1.2.2
- RMServer v2.2.3
- CAL v1.3.3

FIRMWARE

CAL:

- Bug Fixes



Meyer Sound Laboratories Inc.
2832 San Pablo Avenue
Berkeley, CA 94702
www.meyersound.com
+1 510 486.1166

Compass 4.2.2 Release Notes
©2017 Meyer Sound. All rights reserved.

The contents of this document are furnished for informational purposes only, are subject to change without notice, and should not be construed as a commitment by Meyer Sound Laboratories Inc. Meyer Sound assumes no responsibility or liability for any errors or inaccuracies that may appear in this document. Except as permitted by applicable copyright law, no part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, recording or otherwise, without prior written permission from Meyer Sound.