

RELEASE NOTES



COMPASS 4.3.0 UPDATES FOR GALAXY, CAL, AND RMSERVER

Compass 4.3.0 software includes additional features and enhancements.
Compass 4.3.0 software requires the following firmware versions:

- GALAXY Firmware v1.3.0 (All models)
- Bluehorn 816 v1.3.0
- RMServer v2.3.0
- CAL v1.4.0

COMPASS FEATURES & ENHANCEMENTS

GALAXY All Pass Filters:

- The Output Processing Tab adds support for 3 all pass filters for every output.

GALAXY Notification Tab:

- Compass Notification tab adds support to allow access to quick summaries of critical log messages of your GALAXY system. This feature allows the user to see error or log summaries for every device connected to the Compass interface.

RMServer:

- The 488-HP now supports the Ashby 5C and 8C Intelligent DC products.

Bug Fixes and performance improvements

CAL

- CAL default AVB streams are now 24-bit/96 kHz 8-channel AM824 packet format. AM824 supports the transport of multi-channel 24-bit linear audio.

Bug Fixes and performance improvements

RMSERVER

Ashby 5C and 8C:

- RMServer Firmware 2.3.0 includes product support for Ashby 5C and 8C from the MPS-488HP product selection menu.

Bug Fixes and performance improvements



Meyer Sound Laboratories Inc.
2832 San Pablo Avenue
Berkeley, CA 94702
www.meyersound.com
+1 510 486.1166

Compass 4.3.0 Release Notes
©2017 Meyer Sound. All rights reserved.

The contents of this document are furnished for informational purposes only, are subject to change without notice, and should not be construed as a commitment by Meyer Sound Laboratories Inc. Meyer Sound assumes no responsibility or liability for any errors or inaccuracies that may appear in this document. Except as permitted by applicable copyright law, no part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, recording or otherwise, without prior written permission from Meyer Sound.