

# RELEASE NOTES

---



## COMPASS 4.3.6 UPDATES FOR GALAXY, CAL, AND RMSERVER

Compass 4.3.6 software requires the following firmware versions:

- GALAXY Firmware v1.3.4 (All models)
- Bluehorn 816 v1.3.4
- CAL v1.4.0
- RMServer v2.6.0

Firmware NOT Supported in Compass 4.3.6:

- GALAXY v1.3.2 or earlier
- Galileo and Callisto v3.12.0 or earlier
- CAL Firmware 1.3.3 or earlier
- RMServer 2.5.1 or earlier

## COMPASS FEATURES & ENHANCEMENTS

Speaker compatibility:

- ULTRA-X40 supported in RMServer
- UPQ-D1, UPQ-D2, and UPQ-D3 supported in RMServer
- LYON-TPL3 supported in RMServer



Meyer Sound Laboratories Inc.  
2832 San Pablo Avenue  
Berkeley, CA 94702  
[www.meyersound.com](http://www.meyersound.com)  
+1 510 486.1166

Compass 4.3.6 Release Notes  
©2019 Meyer Sound. All rights reserved.

The contents of this document are furnished for informational purposes only, are subject to change without notice, and should not be construed as a commitment by Meyer Sound Laboratories Inc. Meyer Sound assumes no responsibility or liability for any errors or inaccuracies that may appear in this document. Except as permitted by applicable copyright law, no part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, recording or otherwise, without prior written permission from Meyer Sound.