

## RELEASE NOTES

---

# Compass 4.12.0



### OPERATING SYSTEM COMPATIBILITY

---

This version is compatible with MacOS 13 (Ventura) and Windows 11 Professional, 64-bit.

### FIRMWARE COMPATIBILITY

---

- Galileo GALAXY (all models) Firmware v2.7.0 - updated for this release
- RMServer Firmware v2.9.1
- Milan Endpoint Firmware v1.4.0 - updated for this release
- Bluehorn 816 Firmware v2.7.0 - updated for this release
- CAL Firmware v2.2.0



**NOTE:** If upgrading CAL from firmware version 1.5.0 or earlier, please contact Technical Support for specific instructions.

### NEW FEATURES

---

- 2100-LFC Product Integration

### UPDATES / FIXES

---

- Improved IEEE 1722.1 compliance
- Milan Endpoint connection improvements
- Improved behavior of Milan Endpoints with third-party controllers
- Milan stream counter improvements
- Various bug fixes

### KNOWN ISSUES

---

- A small percentage of loudspeakers equipped with RMS modules will not retain their user-entered loudspeaker name when the “Discover All Loudspeakers” button in the Compass Monitoring tab is clicked or the “Discover Inventory” option is selected from the contextual menu in the Compass Monitoring tab. This issue is related to Echelon hardware and is not able to be fixed as we have received the last available Echelon components.

*The contents of this document are furnished for informational purposes only, are subject to change without notice, and should not be construed as a commitment by Meyer Sound Laboratories Inc. Meyer Sound assumes no responsibility or liability for any errors or inaccuracies that may appear in this document. Except as permitted by applicable copyright law, no part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, recording or otherwise, without prior written permission from Meyer Sound.*

---