

RELEASE NOTES



COMPASS 4.3.5 UPDATES FOR GALAXY, CAL, AND RMSERVER

Compass 4.3.5 software requires the following firmware versions:

- GALAXY Firmware v1.3.4 (All models)
- Bluehorn 816 v1.3.4
- CAL v1.4.0
- RMServer v2.5.1

Firmware NOT Supported in Compass 4.3.5:

- GALAXY v1.3.2 or earlier
- Galileo and Callisto v3.12.0 or earlier
- CAL Firmware 1.3.3 or earlier
- RMServer 2.5.0 or earlier

COMPASS FEATURES & ENHANCEMENTS

Open MAPP XT Projects in Compass populates all output processing, Delay Integration, Array Correction and channel labels.

Speaker compatibility:

- UP-4slim Delay Integration
- Ashby Delay Integration
- USW-210P supported in RMServer



Meyer Sound Laboratories Inc.
2832 San Pablo Avenue
Berkeley, CA 94702
www.meyersound.com
+1 510 486.1166

Compass 4.3.4 Release Notes
©2018 Meyer Sound. All rights reserved.

The contents of this document are furnished for informational purposes only, are subject to change without notice, and should not be construed as a commitment by Meyer Sound Laboratories Inc. Meyer Sound assumes no responsibility or liability for any errors or inaccuracies that may appear in this document. Except as permitted by applicable copyright law, no part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, recording or otherwise, without prior written permission from Meyer Sound.